

NOTE: OBLITERATED CORNERS REESTABLISHED
AT THE LOCATIONS ORIGINALLY ESTABLISHED
PER RECORD OF SURVEY NO. 31-12 AS
RECORDED IN BOOK 2 OF RECORD
OF SURVEYS, PAGE 77.

SEC. COR. 520 | 521
529 | 528
USGLO BRASS
CAP



NO SCALE

