


# CORNER RECORD

COUNTY OF MONO T. 9N R. 22E; 23E MDP § MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER ☒ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐  
 CORNER IDENTIFICATION - DATE OF VISIT 20 AUG 1975



Observed and Photographed by M. Allstead

$\frac{1}{4}$  Corner East 36

CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☒

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Roll #1 Frame #8 - Closeup of the bent over pipe + cap looking toward the South

Roll #1 Frame #9 - From 15± ft North of the corner looking south toward Cunningham Lane. The metal object appears to be a large (1.5 ft long 0.8± diam) oil filter

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED: Found USGLO brass cap set on a 1" dia. iron pipe. The station has been disturbed and is bent over towards the NW. Dug out around corner and set wooden diagonals and mound of rocks around it.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☒

STATIONS USED: NGS (USC & GS) ☐ STATE ☒ COUNTY ☐ OTHER ☐ STATION CMLG. #1 STATION  
 ZONE 3 ELEVATION 5076± NORTHINGS (Y) 759,717.28± EASTINGS (X) 2,383,206.73±

SKETCH: (Include reference tie or witness points, remarks and topo of area)

## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 8-20-75 7-25 1978

SIGNED: Rui C. Yfema

L.S. or R.C.E. No. 4468

SEAL

## COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED 5 19 78 AND EXAMINED AND FILED 19

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. 9N22-36-1

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐