



FOUND 5/8" REBAR WITH
C.D.H. PLASTIC CAP, DOWN 0.05M.
THIS PLASTIC CAP WAS A REPLACEMENT
FOR THE PLASTIC CAP "LS 4587" THAT
WAS FOUND DESTROYED ON 7-27-95.
NO CORNER RECORD WAS FILED.
N 661998.927
E 2121509.851

NOT TO SCALE.

C.G.F. = 0.99961137

NOTE:

ALL COORDINATES SHOWN
ARE CCS 83, ZONE 3.
METRIC

OLD R/W
LINE

WILL BE
DESTROYED
BY CONSTRUCTION.

NEW R/W
LINE

FOUND 5/8" REBAR WITH
PLASTIC CAP, "LS 4587"
DOWN 0.05M. PER.
RS 34-64
N 661987.375
E 2121520.991
WILL BE DESTROYED
BY CONSTRUCTION

SET "CALTRANS" ALUM CAP ON A
3/4" x 30" REBAR,
DOWN 0.12M. STAMPED;
"1246+99.057 27.418L 2000".
WITH METAL WITNESS POST 1.0M
TOWARD Q. N 661990.688
E 2121500.861

LV GAS

SET "CALTRANS" ALUM CAP ON
A 3/4" x 30" REBAR, FLUSH.
STAMPED; "1246+99.060
37.423L 2000". WITH
METAL WITNESS POST 1.0M
TOWARD Q.
N 661983.928
E 2121493.485

SET "CALTRANS" ALUM
CAP. ON A 3/4" x 30"
REBAR, FLUSH WITH
AC. STAMPED;
1246+68.963 28.308L
2000. WITH METAL
WITNESS POST
3.0M WEST.
N 661966.982
E 2121523.595