


CORNER RECORD

COUNTY OF ~~MONO~~ MONO T. 1 S R. 28 E MD6 E MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION - DATE OF VISIT 9/21/1977



CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH Ed 1 1/2" O.D.
iron pipe, up 2 3/4", with a 4"x4" USFS boundary marker post 0 1/2' N.,
up 3 3/4", with signs on N. & E. sides of post. Ed old 1"x2" 12" 4' = 11"
of monument


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Pictures Taken Roll #1 Exp #8 Looking N at Mon.
" " #9 Looking SW at Mon.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

* Area has been heavily logged.
 No evidence of bearing
 trees remain at this location.

 4x4 post w/signs
 ○ 1 1/2" O.D. iron pipe

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON 9/21/77
 (SIGNED: [Signature])
 L.S. or R.C.E. No.: [Signature]
 SEAL

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED 9/21/77 1977
 AND EXAMINED AND FILED _____ 19____
 BY: _____
 TITLE: _____
 DOCUMENT No. 1S 28-6-1
 STATEMENT ON BACK OF SHEET
 YES ☐ NO ☐