


REVISED

# CORNER RECORD

Agency Index BK 102 PG 24  
Document Number CR 10628

City of CASTRO VALLEY County of ALAMEDA, California  
Brief Legal Description PU55F6 (FAIRMONT DRIVE EAST OF FOOTHILL BLVD)



## CORNER TYPE

Government Corner ☒ Control  
Meander ☐ Property  
Rancho ☐ Other

Date of Survey 07/24/2017

## COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units Metric ☐ U.S. Survey Foot ☒  
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
Vertical Datum \_\_\_\_\_  
☐ Complies with Public Resources Code §§8801-8819  
☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:  
Corner/  
Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☒ Pre-Construction  
☐ Found and tagged ☐ Reestablished ☐ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

*FOUND COUNTY BRASS CAP MON MARKED "11B" IN MON WELL, DOWN 12",  
SET FOUR MAG NAILS AND TIES TO BJ81B1 (MARKED "11A")  
AND AS SHOWN ON SHEET 2.*

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on JULY 30, 2017

Signed *James N. Landrum* P.L.S. or R.C.E. No. LS 5837



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 20, 2017

and examined and filed 15 MARCH 2018


Signed *Michael Rubner* P.L.S. or R.C.E. No. 6843

Title COUNTY SURVEYOR

County Surveyor's Comment

*REVISED (26/02/2018)*

*SPEC 2279*



PU55F6

NO SCALE

